Siesmic Vulnerability Evaluation

s.n	Owner	Address	Estimated building damage	Posting(Extent of damage)			Comments
				green placard	Yellow placard	red placard	
1	Jagat Nath Khanal	Swyambhu,Ktm	0-1 %	*			Minor hair crack in wall.
2	Dhan bdr. Tamang	Swyambhu,ktm	0-1 %	*			Normal hair crack in ground floor.
3	Kalpana Shrestha	Swyambhu,Ktm	0-1 %	*			Ground floor partition wall to be re-constructed.
4	Keshav Luitel	Kapan, Ktm	None	*			
5	Tirtha Dangol	Swyambhu,Ktm	None	*			Minor crack on wall.
6	Nani Maya Maharjan	Swyambhu,Ktm	None	*			
7	Kailash K. Shrestha	Swyambhu,Ktm	10-30%		*		No. of cracks in staircase, major cracks in ground floor and basement.
8	Gyan bdr. Shrestha	Boudha, ktm	30-60 %			*	Severe cracking of walls and sign of distress preset.
9	Krishna bdr. Lama	Boudha, ktm	60-100 %			*	Ground floor and first floor column failure, big patch just below beam.
10	Subhadra Raj Bhandari	Shantinagar, ktm	0-1 %	*			Minor signs of distress present.
11	Diku Sherpa	Boudha, ktm	0-1 %	*			Minor cracking of walls and sign of distress preset.
12	Pasang Nurbu Sherpa	Boudha, ktm	None	*			Minor cracking of walls and sign of distress preset.
13	Eva Puri	Boudha, ktm	None	*			
14	Galjen Sherpa	Boudha, ktm	None	*			
15	SitaRam Risal	Mitrapark, ktm	0-1 %				Minor cracking of walls and sign of distress preset.
16	Maya Lama	Boudha, ktm	0-1 %	*			Minor cracking of walls and sign of distress preset.
17	Manju Pokharel	Koteshowr,Ktm	None	*			
18	Pragya Sharma	Kapan,Ktm	1-10 %	*			Top floor water tank failure in structure.